



**ATLAS
FIBRE
COMPANY**

3411 Woodhead Dr.
Northbrook, IL 60062
847-674-1234 (p)/847-674-1723 (f)
www.atlasfibre.com
www.atlasfibremachining.com
sales@atlasfibre.com

1. Identification:

Product Name: X, XX, XXX, C, CE, L, LE, N-1

Other/ Generic Names: Phenolic-Cotton Fabric Laminate

Recommended Use: Industrial Use of Thermoset Laminate

Manufacturer: **Atlas Fibre Company**
3411 Woodhead Drive
Northbrook, IL 60062

Emergency Contact Information: Product as shipped is NOT hazardous and is NOT regulated for transportation. For non-transportation emergencies, contact authorities as require by conditions.

2. Hazard(s) Identification:

GHS Hazard Classification: No hazards are associated with this product as shipped. Hazards are associated with product only after further processing (machining, punching) or after thermal decomposition.

Dust generated from further processing or fumes generated from thermal decomposition:

Health, Specific target organ toxicity, single exposure, 3
Health, Skin corrosion/irradiation, 2
Health, Eye damage/irritation, 2B
Physical, Combustible dust

Hazard Pictogram: Not applicable for product as shipped. For dust generated from further processing or fumes generated from thermal decomposition.



Signal Word: Not applicable for product as shipped. For dust generated from further processing or fumes generated from thermal decomposition:

WARNING

**More info about
Phenolics**

**More info about
PROP 65**





**ATLAS
FIBRE
COMPANY**

3411 Woodhead Dr.
Northbrook, IL 60062
847-674-1234 (p)/847-674-1723 (f)
www.atlasfibre.com
www.atlasfibremachining.com
sales@atlasfibre.com

Hazard Statement(s): not applicable for product as shipped. For dust generated from further processing or fumes generated from thermal decomposition:

May cause respiratory irritation
Causes skin irritation
Causes eye irritation
May form combustible dust concentrations in air

Precautionary Statement(s):

Prevention: For dust generated from further processing or fumes generated from thermal decomposition:

Wear protective gloves and clothing to avoid dust contact with skin, wear protective glasses to avoid dust contact with eyes, avoid breathing dust or fumes, process only when adequate ventilation and dust controls are in place.

Response: For dust generated from further processing or fumes generated from thermal decomposition:

If on skin, wash thoroughly with water. If skin irritation persists, consult a physician.
Remove contaminated clothing and wash before reuse.
If in eyes, irrigate cautiously with flowing water for 15 minutes, remove contact lenses when applicable. If eye irritation persists, consult a physician.
If overcome by dust or fumes, relocate to fresh air and keep comfortable while breathing.
Consult a physician if not breathing or if feeling unwell.
If dust becomes airborne, reduce levels below concentrations required to cause explosive conditions.

Storage: The product as shipped requires no specific storage considerations.

Disposal: The product as shipped is not considered hazardous. Be sure to follow all local, state and federal regulations when considering a disposal method.

3. Composition/ Information On Ingredients:

No hazardous ingredients at reportable levels are present in the product as shipped.

**More info about
Phenolics**


**More info about
PROP 65**

MGMT-0031



Industrial Plastic Supply
2240 S. Dupont Drive
Anaheim, CA 92806
(866-832-9315)
www.iplasticsupply.com

Rev: A



**ATLAS
FIBRE
COMPANY**

3411 Woodhead Dr.
Northbrook, IL 60062
847-674-1234 (p)/847-674-1723 (f)
www.atlasfibre.com
www.atlasfibremachining.com
sales@atlasfibre.com

4. First Aid Measures:

For dust generated from further processing or fumes generated from thermal decomposition:

If on skin, wash thoroughly with water. If skin irritation persists, consult a physician. Remove contaminated clothing and wash before reuse.

If in eyes, irrigate cautiously with flowing water for 15 minutes, remove contact lenses when applicable. If eye irritation persists, consult a physician.

If overcome by dust or fumes, relocate to fresh air and keep comfortable while breathing. Consult a physician if not breathing or if feeling unwell.

Advice to physician : Treat symptomatically

5. Fire Fighting Measures:

May give off toxic gases of CO, CO₂, and Phenol when burning or headed to point of thermal decomposition. Fire fighters should wear proper protective equipment and positive pressure self-contained breathing apparatus. Use water, CO₂ or dry chemical to fight fire.

6. Accidental Release Measures:

Material as shipped is in solid form. Accidental release is not normally a consideration.

7. Handling and Storage:

Handle only with proper protective equipment or in environments where adequate ventilation is available to avoid exposure to dust and fumes and which can reduce airborne concentrations to levels sufficiently low to avoid combustion. The product as shipped requires no specific storage considerations.

8. Exposure Controls/Personal Protection:

Use local exhaust ventilation to control dust. Use protective gloves and protective clothing if dust will come in contact with skin. Use protective glasses if dust will come in contact with eyes. If dust exposure will exceed exposure guidelines, use an approved dust respirator.


**More info about
Phenolics**

**More info about
PROP 65**

MGMT-0031



Industrial Plastic Supply
2240 S. Dupont Drive
Anaheim, CA 92806
(866-832-9315)
www.iplasticsupply.com



**ATLAS
FIBRE
COMPANY**

3411 Woodhead Dr.
Northbrook, IL 60062
847-674-1234 (p)/847-674-1723 (f)
www.atlasfibre.com
www.atlasfibremachining.com
sales@atlasfibre.com

Exposure Guidelines:

Ingredient Name:	CAS #	ACGIH TLV	OSHA PEL (TWA)
Total Dust	N/A	N/A	15mg/m ³

9. Physical and Chemical Properties:

Form: Solid, flat sheet or rod, color dependent on pigment
 Odor (if any): Possible slight phenolic
 Specific Gravity: 1.35

10. Stability and Reactivity:

This product is stable under expected handling and storage conditions. Incompatibilities have not been determined. If heated in excess of 300° C, products of combustion could include: Phenol, CO and CO₂.

11. Toxicological Information:

No data available

12. Ecological Information:

No data available

13. Disposal Considerations:

Product as shipped is NOT considered a RCRA hazardous waste. However, disposal must be made in accordance with all local, state and federal regulations

14. Transport Information

Product as shipped is NOT a DOT regulated material.

**More info about
Phenolics**

**More info about
PROP 65**



Industrial Plastic Supply
2240 S. Dupont Drive
Anaheim, CA 92806
(866-832-9315)
www.iplasticsupply.com



**ATLAS
FIBRE
COMPANY**

3411 Woodhead Dr.
Northbrook, IL 60062
847-674-1234 (p)/847-674-1723 (f)
www.atlasfibre.com
www.atlasfibremachining.com
sales@atlasfibre.com

15. Regulatory Information:

Specific regulatory considerations should be addressed as they arise. Due to changing regulatory environments, it is not possible to list all considerations.

16. Other Information:

Revision Data: June 26, 2015

END OF SAFETY DATA SHEET

**More info about
Phenolics**

**More info about
PROP 65**

MGMT-0031



Industrial Plastic Supply
2240 S. Dupont Drive
Anaheim, CA 92806
(866-832-9315)
www.iplasticsupply.com

Rev: A